


Field Service Report



Applied Biosystems BV,
 Belgisch bijkantoor
 Surkekaai, 1
 1500 Halle, Belgium
 Tel: +32 (0)2 532 44 84
 Fax: +32 (0)2 582 18 86

Customer	Université Catholique de Louvain
Purchase Order No.	SM02
Order Type	Maintenance Activity
Service Order No.	SPAS-8BSDNY

Address	Université Catholique de Louvain
City	BRUXELLES
, Post Code,	BE, 1200, BE
Contact	Nyabl Omar
Tel	-

Model No	STEPONEPLUS	Contract No	15322151
Serial No	272002704	Contract Type	Warranty
Equipment No	00000000010619743	Contract Expiry	21/03/2011

Order Description	verification StepOnePlus after fire
-------------------	-------------------------------------

Date	03/12/2010	Engineer	Steven Paeps - BE103089
------	------------	----------	-------------------------

Customer Signature	<i>[Signature]</i>	Date	03/12/2010
Engineer Signature	<i>[Signature]</i>	Date	3/12/2010

Ce n'est pas une facture. Tous les montants peuvent être sujets au changement ou à la variation.
 Dit is geen Rekening. Alle bedragen kunnen voor wijzigingen vatbaar zijn of variatie.

Customer	Université Catholique de Louvain
Purchase Order No.	...
Order Type	SM02
Service Order No.	SPAS-8BSDNY
Maintenance Activity	REP

Work Description
 3/12/2010 SP - 3 dec 2010
 StepOne Plus inspection/verification after fire in the lab . Instrument interior is completed covered by dark dust/debris from fire.
 Useless to clean visible parts as mostlikelyly electronic and no accessible components are permanently damaged (pca controller, optic lenses, ccd camera,...)
 Unable to repair the step one plus sn 272002704. Instrument should be replaced.

Engineer Parts Consumption	Material	Material Description	Qty
			0

Local Office Parts Consumption	Material	Material Description	Qty
			0

Activity	Start Date	End Date	Hours
			0